



## ASBESTOS SURVEY REPORT

Survey Undertaken by:

Survey Ref No :  
Property Ref :  
Comments :

Area/room	Floor	Description	Asbestos Type	Product Type	Notes	Licensed Asbestos contractor to be used
Bathroom:	1st	Toilet Cistern	No Asbestos Detected	N/A		N/A
Bathroom:Ceiling	1st	Textured Coating	Chrysotile	Textured Coating		No
Bathroom: Int Wall	1st	Soil/Vent Pipe Int	Presumed Chrysotile	Cement Product		No
Bed 1: Ceiling	1st	Textured Coating	Chrysotile	Textured Coating		No
Bed 2: Ceiling	1st	Textured Coating	Chrysotile	Textured Coating		No
Bed 3: Ceiling	1st	Textured Coating	Chrysotile	Textured Coating		No
Hall: Ceiling	Grnd	Textured Coating	Chrysotile	Textured Coating		No
Hall: Floor	Grnd	Floor Tiles	Chrysotile	Flooring Material		No
Kitchen:Ceiling	Grnd	Textured Coating	Chrysotile	Textured Coating		No
Kitchen:Ceiling	Grnd	Boiler Flue	Presumed Chrysotile	Cement Product		No
Kitchen:Floor	Grnd	Floor Tiles	Chrysotile	Flooring Material		No
Kitchen: Under Sink	Grnd	Pre 1995 Sink Pad	Chrysotile	Bitumen		No
Landing:Ceiling	1st	Textured Coating	Chrysotile	Textured Coating		No
Lounge:Ceiling	Grnd	Textured Coating	Chrysotile	Textured Coating		No
Lounge:Floor	Grnd	Floor Tiles	Chrysotile	Flooring Material		No
Main Building:Ceiling	External	Board/Panel	Presumed Amosite	Board	Surface treatment = Encapsulated AIB	Yes
Main Building:Ext Wall	External	Board/Panel	Presumed Amosite	Board	Surface treatment = Encapsulated AIB	Yes
Main Building:Ext Wall	Roof	Tile Hanging	Presumed Chrysotile	Cement Product		No
Main Building:Ext Wall	External	Soil/Vent Pipe Ext	Presumed Chrysotile	Cement Product		No

**PLEASE PLACE THIS REPORT IN A LOCATION CONVENIENT FOR CONTRACTORS TO VIEW I.E. ADJACENT TO GAS/ELECTRIC METER**